Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW2357/1

Work Order Type: Weatherization

Audit Name: 12012NW2357

CLIENT INFORMATION

Client Name: Address:

Client ID: 12012NW2357

Alt. Client ID:

AGENCY INFORMATION

Agency: Northwest Tn. Economic Development Council Agency Phone: (731) 364-3228

Address: 231 South Wilson St. **Fax:** (731) 364-5029

Dresden, TN 38225-1312 Email Address:

Agency Contact: Woods, Max Work Phone: (731) 286-0332

Cell Phone: (731) 676-1414

Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Measures

Measure 1 Build	d/Insulate Stairway Bo	x		Componen	nts			Inspecte
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail							1	
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:				L			L	
Measure 2 Door Comment Door #1		erstrin		Componen	its			Inspecte
	Thresh	old			la als)			
	Thresh	old	k arour	nd deadbolt	•		Actual	
	Thresh Caulk	old		Estimated	•	Qty	Actual Unit Cost	Total
# Material / Labor	Thresh	old (Also caul	Qty		<u> </u>	Qty	Actual Unit Cost	Total
# <i>Material / Labor</i> 0 Unspecified	Thresh Caulk Description / Comment	old (Also caul <i>Unit</i> s	Qty	Estimated	<u> </u>	Qty		Total
# Material / Labor	Thresh Caulk Description / Comment	old (Also caul <i>Unit</i> s	Qty	Estimated	<u> </u>	Qty		Total
# <i>Material / Labor</i> 0 Unspecified	Thresh Caulk Description / Comment	old (Also caul <i>Unit</i> s	Qty	Estimated	<u> </u>	Qty		Total
# <i>Material / Labor</i> 0 Unspecified	Thresh Caulk Description / Comment	old (Also caul <i>Units</i> Each	Qty 1	Estimated	<u> </u>			Total

	Front Door Weather Thresho Caulk e open and close free	ld	net					
	e open and close free	ly over car	net					
# Material / Labor			POL					
# Material / Labor L				Estimated	<u> </u>		Actual	
# Waterial / Labor 1	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Visc Material	Each	1					
Other Detail								
			Measur	e Sub Total:		:	Sub Total:	
Measure 4 Door # Comment Door #3 E	Back Door Weath Thresh	nold		Component	lock)			Inspected
				Estimated			Actual	
	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail						l		
			Measur	e Sub Total:			Sub Total:	

Measure 5 Ins	stall Ceiling in Furnace C	loset		Componen	ts		ı	Inspected
	ceiling in furnace closet co /seal around supply duct	eiling App	rox 3' :	< 4'				
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Unspecified	Misc Material	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Comment Foam Pack/	Foam head of tub(From (•	(2) Bat	<i>Componen</i> h	ts		,	Inspected
Comment Foam Pack/	Plumbing Penetrations	Crawlspac	(2) Bat	•	ts		ı	Inspected
Comment Foam Pack/ Foam	Plumbing Penetrations Representations Representations	Crawlspac	(2) Bat e)	h			Actual	Inspected
Comment Foam Pack/ Foam	Plumbing Penetrations Repair Registers from Registe	Crawlspac	(2) Bat e)	h und wall		Qty		Inspected
Comment Foam Pack/ Foam Foam # Material / Labor 0 Miscellaneous	Plumbing Penetrations Repair Registers from Repetration in furnace closes	Crawlspac Attic (7) set floor a	(2) Bate e) nd aro	h und wall Estimated	1	Qty	Actual	
Comment Foam Pack/ Foam Foam # Material / Labor 0 Miscellaneous Supplies	Plumbing Penetrations Repair Registers from Penetration in furnace closs	Crawlspac Attic (7) set floor a <i>Units</i>	(2) Batese) and around the set of the set o	h und wall Estimated	1	Qty	Actual	
Comment Foam Pack/ Foam Foam # Material / Labor 0 Miscellaneous	Plumbing Penetrations Repair Registers from Penetration in furnace closs	Crawlspac Attic (7) set floor a <i>Units</i>	(2) Batese) and around the service of the service	h und wall Estimated	1	Qty	Actual	
Comment Foam Pack/ Foam Foam # Material / Labor 0 Miscellaneous Supplies	Plumbing Penetrations Repair Registers from Penetration in furnace closs	Crawlspac Attic (7) set floor a <i>Units</i>	(2) Batese) and around the service of the service	h und wall Estimated	1	Qty	Actual	
Comment Foam Pack/ Foam Foam # Material / Labor 0 Miscellaneous Supplies	Plumbing Penetrations Repair Registers from Penetration in furnace closs	Crawlspace Attic (7) set floor a Units Each	(2) Batese) nd around Qty 1	h und wall Estimated	1		Actual	

	Measure 7 DWF	H Pipe Insulation			Componen	its			Inspected
C	Comment								
					Estimated	/		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail						,		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 8 DWF	H Tank Insulation			Componen	nts			Inspected
	Measure 8 DWH	I Tank Insulation			Componen Estimated			Actual	Inspected
C		d Tank Insulation Description / Comment	Units	Qty	-		Qty		Inspected Total
<i>C</i>	Comment		<i>Units</i> Each		Estimated	1	Qty	Actual	
# 1	Comment Material / Labor Hot Water	Description / Comment		Qty	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Hot Water Equipment	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1		Actual	
C # 1	Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
C # 1	Material / Labor Hot Water Equipment Labor Other Detail	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure	9 Floo	r Ins. R-19			Componer	ts F1			Inspected
Commen	<i>t</i> 16 " Cer	nters							
					Estimated	1		Actual	
# Material	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulatio	on	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1350					
Other Deta	ail								
				Measure	Sub Total:] ;	Sub Total:	
Field No	tes:								
Commen	<i>t</i> Existing	er Heat) H.W.W. Does not work taped in and falls out. T				o-Off whe		f Actual	
# Material	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health a		-	Each	1					
2 Labor		Labor	Hour	1					
Other Deta	ail								
Other Deta	ail								
Other Deta	ail								
Other Deta	ail			Measure	e Sub Total:			Sub Total:	
Other Deta				Measure	Sub Total:			Sub Total:	

Report Run On: 5/19/2010

	Measure 11 Fix ((Attic	Chimney/Flue Shielding	Incorrec	t	Componen	ts			Inspected
C	Comment Block/Se	eal Flue Pipe							
					Estimated	<u>'</u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Chimney / flue shielding	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail								
				Measur	e Sub Total:] .	Sub Total:	
	Measure 12 Fix I Comment	mproper Venting (Cloth	es Dryer))	Componen Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty					
	Health and Safety Items		Each			Total	Otv		Total
2	Labor	Equipment		1	Unit Cost	Total	Qty	Unit Cost	Total
	Labor	Labor	Hour	1		Total	Qty		Total
	Other Detail		Hour			Total	Qty		Total
			Hour			Total	Qty		Total
			Hour			Total	Qty		Total
				1	re Sub Total:	Total			Total

ı	<i>Measur</i> e 13 Fix I Fan	mproper Venting Kitch	en Exhau	st	Componen	rts			Inspected
С	comment Vent exi	sting Vent-A-Hood out th	nru roof						
		3			Estimated	ı		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
Г									
				Measur	e Sub Total:			Sub Total:	
	Exh	mproper Venting of Ba aust Fan Existing bath exhaust o Hall Bath Master Bath		of	Componen			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety Items	-	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
L				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Ме	asure 15 Fix V	Viring Problems (Attic)			Componer	nts			Inspected
Con	nment (3) Impro	oper Wiring Connections (2) J-box covers (1) J-box and cover							
					Estimated	d		Actual	
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	ealth and Safety ems	Equipment	Each	1					
2 L a	abor	Labor	Hour	1					
Othe	er Detail								
				Measur	e Sub Total:] ;	Sub Total:	
Fie	eld Notes:								
		or Barrier Needed ement/Crawlspace) .ft.			Componer	nts			Inspected
					Estimated	d		Actual	
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	ealth and Safety ems	Basement / crawlspace vapor barrier	Each	1					
2 L a	abor	Labor	Hour	1					
Othe	er Detail								
				Measur	e Sub Total:] ;	Sub Total:	
Fie	eld Notes:								
			Work O	der Gra	nd Total:		Gran	d Total:	